| Author | Date | Title | Bate Stamp No. |
|--|------------|--|-----------------|
| AECOM Technical Services, Inc. | 8/5/2009 | Work Plan for Characterization of Nature and Extent of VOC and TPH Impact, Southwestern Boundary at Fullerton Crossing, 601-629 South Placentia Avenue, Fullerton, CA | AR04010-AR04021 |
| AECOM Technical Services, Inc. | 9/14/2009 | Report of Subsurface Soil Investigation Findings, Southwestern Site Boundary, Fullerton Crossings Site, 601-629 South Placentia Avenue, Fullerton, CA | AR00389-AR00414 |
| Camp Dresser & McKee Inc. | 4/30/1991 | Phase II Environmental Assessment of the MDC Center, Fullerton, CA | AR00148-00351 |
| County of Orange Health Care Agency | 10/30/1995 | MDC Center Parcel 1 (Exterior) and Parcel 2 of Parcel Map 90-423, 675 South Placentia Ave., Fullerton, CA 92631 | AR00356-AR00357 |
| County of Orange Health Care Agency | 7/3/2000 | Former MDC Center, Parcel 1 Interior - Process Line Pit and Lumber Areas, 601-629 South Placentia Avenue, Fullerton, CA 92831 | AR00010-AR00011 |
| Earth Tech/AECOM | 5/7/2008 | Subsurface Investigation Workplan, Area of Northern Four Underground Storage Tanks, Fullerton Crossings Site, 601-629 South Placentia Ave., Fullerton, CA | AR03856-AR03872 |
| Earth Tech/AECOM | 7/28/2008 | Closure Report, Summary of Sampling Events, Removal of Three Southern Underground Storage Tanks, Fullerton Crossing Site, 601-629 South Placentia Ave., Fullerton, CA | AR02790-AR02928 |
| Earth Tech/AECOM | 8/11/2008 | Closure Report, Summary of Sampling Events, Removal of Underground Piping Network, Fullerton Crossing Site, 601-629 South Placentia Ave., Fullerton, CA | AR03084-AR03285 |
| Earth Tech/AECOM | 12/2/2008 | Summary Report, Results of Subsurface Investigation, Soil and Groundwater Sampling, Area of Former Northern Underground Storage Tanks, Fullerton Crossings Site, 601-629 South Placentia Ave., Fullerton, CA | AR03286-AR03445 |

| Earth Tech/AECOM | 10/07 - 7/08 | Compendium of Analytical Data In-Place Soil Samples | AR01175-AR01446 |
|-------------------------------------|-----------------|---|-----------------|
| Earth Tech/AECOM | 10/07 - 7/08 | Compendium of All Analytical Data for Soil Samples | |
| EarthTech | May-2006 | Soil Vapor Investigations and Health Risk Analysis, Proposed Sam's Club, Home Depot and Sams' Club Fuel Center, Fullerton Crossing, Fullerton, CA | AR00012-AR00147 |
| EarthTech | 3/14/2008 | Report, Summary of Sampling Events, Removal of Four Underground Storage Tanks, Fullerton Crossing Site, 601-629 South Placentia Ave., Fullerton, CA | AR03958-AR04009 |
| Eckland Consultants, Inc. | 12/9/1999 | Limited Phase II Subsurface Investigation, Former MDC Center, 601-675 South Placentia Avenue, Fullerton, CA 92831 | AR00358-AR00365 |
| Eckland Consultants, Inc. | 5/18/2000 | Additional Phase II Subsurface Investigation, Former MDC Center, 601-675 South Placentia Avenue, Fullerton, California 92831 | AR00001-AR00006 |
| Kennedy/Jenks Consultants | October 2009 | Historic Aerials - 1968, 1977, 1995 | AR02951-AR02952 |
| McDonnell Douglas Realty Company | 10/17/1995 | Case Closure Report | AR00352-AR00355 |
| MRES America Fund, MDC | 6/23/2000 | OCHCA Case Summary/Closure Rationale | AR00007-AR00009 |
| N/A | N/A | Aerial Photo – 1928 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 1938 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 1947 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 1953 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 1968 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 1977 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 1990 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 1995 | AR04022-AR04030 |
| N/A | N/A | Aerial Photo – 2002 | AR04022-AR04030 |
| PES Environmental, Inc. | 1/17/2007 | Groundwater Investigation Report, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02979-AR03083 |

| PES Environmental, Inc. | 6/19/2007 | Groundwater Investigation Report, April 2007 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR01497-AR01568 |
|-------------------------|------------|---|-----------------|
| PES Environmental, Inc. | 10/30/2007 | Groundwater Monitoring Report, July 2007 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR01569-AR01626 |
| PES Environmental, Inc. | 1/9/2008 | Additional Investigation - Soil Vapor Sampling Program, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02542-AR02549 |
| PES Environmental, Inc. | 4/24/2008 | Additional Investigation Report, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR01627-AR01886 |
| PES Environmental, Inc. | 4/2/2009 | Soil Vapor Investigation Report, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR01887-AR01944 |
| PES Environmental, Inc. | 9/2/2010 | Additional Soil and Groundwater Investigation Report, Southern Fence Line, Former Aerojet Facility, 601 South Placentia Ave., Fullerton, CA | AR02550-AR02789 |
| PES Environmental, Inc. | 8/11/2011 | Soil Removal Report, Southern Fence Line, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR03446-AR03791 |
| PES Environmental, Inc. | 3/17/2014 | Destruction of Groundwater Monitoring Well PW-3, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, California | AR00562-AR00577 |
| PES Environmental, Inc. | 6/14/2016 | Additional Groundwater Investigation Report, Former Aerojet Facility, 601 South Placentia Ave., Fullerton, CA | AR01945-AR02107 |
| PES Environmental, Inc. | 9/14/2016 | Groundwater Monitoring Report, July 2016 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02108-AR02170 |
| PES Environmental, Inc. | 11/9/2016 | Groundwater Monitoring Report, October 2016 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02171-AR02234 |

| PES Environmental, Inc. | 2/9/2017 | Groundwater Monitoring Report, January 2017 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02235-AR02305 |
|---|------------|---|-----------------|
| PES Environmental, Inc. | 1/10/2018 | Conceptual Site Model Information Request, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, California | AR00366-AR00388 |
| PES Environmental, Inc. | 1/26/2018 | Groundwater Monitoring Report, December 2017 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR01447-AR01496 |
| PES Environmental, Inc. | 3/29/2018 | Groundwater Monitoring Report, February 2018 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02306-AR02357 |
| PES Environmental, Inc. | 7/17/2018 | Groundwater Monitoring Report, May 2018 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02358-AR02419 |
| PES Environmental, Inc. | 10/15/2018 | Groundwater Monitoring Report, August 2018 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02420-AR02493 |
| PES Environmental, Inc. | 1/25/2019 | Groundwater Monitoring Report, December 2018 Groundwater Monitoring Event, Former Aerojet Facility, 601 South Placentia Avenue, Fullerton, CA | AR02494-AR02541 |
| Santa Ana Regional Water Quality Control Board | 6/17/2014 | Determination of No Further Action (NFA) for Soil - Parcel 1, Fullerton Crossings, 625 South Placentia Avenue, Fullerton, CA | AR02929-AR02950 |
| Santa Ana Regional Water Quality Control Board | 10/25/2018 | Conditional No Further Action For Soil at Fullerton Crossings Parcels 2, 3, and 4; at 603-613 & 633-663 South Placentia Avenue, Fullerton | AR02953-AR02978 |
| TOR Environmental, Inc. | 7/3/2013 | Summary of Former Home Depot Demolition Remedial Activities at Fullerton Crossings | AR03873-AR03874 |
| TOR Environmental, Inc. | 7/3/2013 | Email from Jeffrey Borum to Patricia Hannon, Fullerton Crossings - Analytical Results Revised | AR03875-AR03946 |

| TOR Environmental, Inc. | 7/3/2013 | Email from Jeffrey Borum to Patricia Hannon, Fullerton Crossings - Soil Sampling and Feature Maps | AR03947-AR03957 |
|-------------------------|-----------|---|-----------------|
| TOR Environmental, Inc. | 2/7/2014 | Report of Soil Gas Survey and Limited Health Risk Assessment, Future Sam's Club Building Footprint, Fullerton Crossings Site, 601 – 629 South Placentia Avenue Fullerton, California | AR00415-AR00561 |
| TOR Environmental, Inc. | 4/30/2014 | Soil Removal Action Completion Report, Fullerton Crossings Parcel 1, 625 S. Placentia Ave., Fullerton, CA 92831 | AR03792-AR03855 |
| TOR Environmental, Inc. | 5/9/2017 | Report of Limited Soil Gas Survey and Health Risk Assessment, Future Shops 1 Building Footprint, Fullerton Crossings Site, 601-629 S. Placentia Ave., Fullerton, CA 92831 | AR00578-AR00666 |
| TOR Environmental, Inc. | 7/17/2017 | Soil Removal Action Completion Report, Fullerton Crossings Parcels 2-4, 603-613 & 633-663 S. Placentia Ave., Fullerton, CA 92831 | AR00667-AR01446 |